

Map Check Report

Report Created: Tuesday, June 10, 2025
Time: 2:17:46 PM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-
pw.bentley.com_ohiodot-pw-
02\beth.sanders@dot.ohio.gov\d0328760\114960_BR001_96RW.dgn

Last Revised: 6/10/2025 14:16:17

**Input Grid
Factor:**

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 10SH2

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	S20.050°W	53.850		
HPI	(HPI)	-50.586	-18.462	0.000
	S88.249°W	30.000		
HPI	(HPI)	-51.503	-48.448	0.000
	N1.751°W	25.000		
HPI	(HPI)	-26.515	-49.212	0.000
	N74.397°W	83.820		
HPI	(HPI)	-3.969	-129.943	0.000
	N88.249°E	130.000		
POT	(POT)	0.003	-0.004	0.000

Northing Error: 0.003 ft
Easting Error: -0.004 ft
Closing Direction: S47.034°E
Closing Distance: 0.005 ft
Closed Area: 3000.226 sq ft 0.069 ac
Perimeter: 322.670 ft
Precision: 66342 : 1