

Map Check Report

Report Created: Tuesday, June 10, 2025
Time: 2:20:11 PM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d0328760\114960_BR001_96RW.dgn

Last Revised: 6/10/2025 14:18:42

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 10T

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	S66.448°W	53.850		
HPI	(HPI)	-21.518	-49.364	0.000
	S86.340°W	150.080		
HPI	(HPI)	-31.099	-199.138	0.000
	N20.050°E	26.930		
HPI	(HPI)	-5.801	-189.905	0.000
	N88.249°E	190.000		
POT	(POT)	0.005	0.006	0.000

Northing Error: 0.005 ft
Easting Error: 0.006 ft
Closing Direction: S51.718°W
Closing Distance: 0.008 ft
Closed Area: 3750.684 sq ft 0.086 ac
Perimeter: 420.860 ft
Precision: 54079 : 1