

Map Check Report

Report Created: Monday, June 23, 2025
Time: 1:01:04 PM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d1050817\119666_BR002.dgn

Last Revised: 6/23/2025 12:45:13

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 10-SH1

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	S88.775°W	185.000		
HPI	(HPI)	-3.955	-184.958	0.000
	N53.237°E	43.010		
HPI	(HPI)	21.787	-150.502	0.000
	N88.775°E	50.000		
HPI	(HPI)	22.856	-100.513	0.000
	S77.189°E	103.080		
POT	(POT)	-0.002	0.001	0.000

Northing Error: -0.002 ft
Easting Error: 0.001 ft
Closing Direction: N26.798°W
Closing Distance: 0.002 ft
Closed Area: 2937.348 sq ft 0.067 ac
Perimeter: 381.090 ft
Precision: 223135 : 1