

Map Check Report

Report Created: Monday, June 23, 2025
Time: 1:05:15 PM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d1050817\119666_BR002.dgn

Last Revised: 6/23/2025 13:03:25

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 11-SH1

Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	S47.299°W	30.200		
HPI	(HPI)	-20.481	-22.194	0.000
	S88.775°W	50.000		
HPI	(HPI)	-21.550	-72.183	0.000
	N62.741°W	41.940		
HPI	(HPI)	-2.341	-109.465	0.000
	N88.775°E	109.490		
POT	(POT)	-0.000	-0.000	0.000

Northing Error: -0.000 ft
Easting Error: -0.000 ft
Closing Direction: N66.241°E
Closing Distance: 0.000 ft
Closed Area: 1595.020 sq ft 0.037 ac
Perimeter: 231.630 ft
Precision: 1001394 : 1