

Map Check Report

Report Created: Monday, June 23, 2025
Time: 1:08:32 PM

Project: Design

Description:

File Name: c:\users\eellison\appdata\local\bentley\projectwise\workingdir\ohiodot-pw.bentley.com_ohiodot-pw-02\beth.sanders@dot.ohio.gov\d1050817\119666_BR002.dgn

Last Revised: 6/23/2025 13:06:14

Input Grid Factor:

Note: All units in this report are in feet unless specified otherwise.

Alignment Name: 11-T1
Alignment Description:

Type	Point Name/ Direction	Northing/ Length	Easting	Elevation
POT	(POT)	0.000	0.000	0.000
	S51.471°W	132.000		
HPI	(HPI)	-82.224	-103.263	0.000
	S88.775°W	45.000		
HPI	(HPI)	-83.186	-148.253	0.000
	N32.789°W	70.420		
HPI	(HPI)	-23.986	-186.388	0.000
	S62.741°E	41.940		
HPI	(HPI)	-43.195	-149.106	0.000
	N88.775°E	50.000		
HPI	(HPI)	-42.126	-99.117	0.000
	N47.299°E	30.200		
HPI	(HPI)	-21.645	-76.923	0.000
	N1.225°W	20.000		
HPI	(HPI)	-1.650	-77.351	0.000
	N88.775°E	77.370		
POT	(POT)	0.004	0.001	0.000

Northing Error: 0.004 ft
Easting Error: 0.001 ft
Closing Direction: S19.466°W
Closing Distance: 0.004 ft
Closed Area: 5858.552 sq ft 0.134 ac
Perimeter: 466.930 ft
Precision: 104775 : 1