

9-23-25/95034

109

ODOT Site 7

ODT on site IN
16587 16647 16717
16656

ET

LC

7AM

4PM

RTK Base set on Control
#100 / 2m Height
Intell started @ 8:46 AM
Ended @ 1:53 PM

9

TO4 = 14792660

RTK Rover check into
Control #101 / 2m Rod
stored as 101CHK
 $N = -0.027'$ $E = -0.018'$ $V = -0.056'$

#503 SFNF

#504 Found G504
Vertical Clay tile with
Concrete Rebar No Disc
(Mag Pull shot)

SOS Found G505
Conc Mon, No Disc, 3/8" Rebar
Center / shot

(110)

506 Found 6506
Conc Mon, NO Disc
3/8" Rebar Shot

508 Found 6508
Conc Mon, NO Disc
3/8" Rebar Shot

#510 SFNF

548 SFNF

547 Found 6547
5/8" Rebar, Bent East
Spun, Bottom straight, Hole shot
Replaced into original hole

546 Found 6546
5/8" Rebar, Bent South
shot @ North side Bend

545 SFNF

TOPO Points = 7001 - 7064

RTK Rover checkout into #103

$N = 0.014$ $E = -0.041$ $V = 0.050$