

CRS:	COL-Dresden Avenue Phase 2	PID:	121577	Date:	02/19/25
------	----------------------------	------	--------	-------	----------

ENVIRONMENTAL SOS

Task	Task#	Required	Preparer	Comments
CE Level: C2	3.5.A	X	D11	
Purpose and Need Statement	1.3.G			
Cultural Resource SRF	2.2.B	X	D11	
Phase I Cultural Archaeological	3.1.A			
Phase I Cultural History Arch	2.2.I			
Phase II Cultural History Arch	3.1.B			
Section 4(f) Determination/Coord	2.2.F & 3.1.C			
Recreational Boating Review Form	NA			
Ecological Survey Level: 1	2.2.C	X	Consultant	
Mussel Survey	3.1.Q			
Section 9/Section 10 Coordination	3.1.M.C			
Permit Determination Request	3.1.M.A	X	Consultant	
Section 404 PCN	3.1.M.B	X	Consultant	If-authorized
404 Individual Permit	3.1.M.D			
OEPA Director's Authorization App	3.1.M.H			
401 Water Quality Application	3.1.M.C			
Flood Plain Coordination	2.3.H.A			
Scenic River Coordination	NA			
Public Involvement	2.2.A & 2.6.A	X	D11	Web Release
FCIR Form	3.1.E			
RMR Screening	2.2.D	X	Consultant	
RMR Assessment	3.1.D			
RMR Investigation	3.1.O	X	Consultant	If-authorized on two properties
Noise Analysis	2.2.G & 2.2.H			
Air Quality Analyses	3.1.P			
Asbestos Inspection	NA			

CRS:	COL-Dresden Avenue Phase 2	PID:	121577	Date:	02/19/25
------	----------------------------	------	--------	-------	----------

ENVIRONMENTAL SOS

Additional Comments:
Based on 02/19/25 field scoping review. Multiple streams and SWH noted during site visit. Multiple shallow culverts carrying streams within the project limits.

